

Flintshire Buildings at Risk 2011 Survey - Risk Categories 1 and 2

BUILDING/STRUCTURE NAME	COMMUNITY	GRADE	Status
Risk Score 1 - Grave Risk			
Dingle Cottage, Gadlys	Bagillt	II	One of 4 cottages - 2 have been restored to date with lbc approval
Ebenezer Chapel	Brynford	II	lbc approval renewed 2014
Lime kilns at Bryn Mawr	Brynford	II	Subject to consolidation works with external funding - lbc approved - no longer at risk
Bath House at Coed Du	Cilcain	II	See case study
Engine House at Hendre Quarry	Cilcain	II	
Bryn Awel, Pentre Halkyn	Halkyn	II	lbc approval & under restoration
Brick Kiln and Stack at Hendre Quarry	Halkyn	II	Listed in state of disrepair
Ore Dressing Shed at Hendre Quarry	Halkyn	II	Listed in state of disrepair
Taylor's Shaft Engine House at Hendre Quarry	Halkyn	II	Listed in state of disrepair
Ice House East of Registry Office, Rectory Lane	Hawarden	II	FCC
Former Stable Block at Castle Hill Farm, Ewloe	Hawarden	II	lbc approved & on site
Former Dovecote S of Leeswood Hall	Leeswood	II	Derelict - See case study
Ice House at Gyrn Castle	Llanasa	II	
Stable block at Home Farm, Talacre Abbey	Llanasa	II	Discussions but no progress
Mostyn Hall Ice House	Mostyn	II	Discussions but no progress
Gate piers and garden wall at Isglan Farm	Mostyn	II	
Barn and cow house at Isglan Farm	Mostyn	II	
Piggeries at Nerquis Hall	Nercwys	II	lbc appl under consideration
Dovecot at The Tower	Nercwys	II	
Adjoining Farm Buildings to S, Trefrwd Farm	Nercwys	II	lbc approved
Former Women's Land Army Hostel	Sealand	II	Discussions but no progress
Siamber Wen, Trelawnyd	Trelawnyd & Gwaenysgor	II	For Sale - See case study
Pentre Mawr Farmhouse , Trelawnyd	Trelawnyd & Gwaenysgor	II	Listed as derelict building
Former Cartshed in rear yard of Llys Mair	Whitford	II	Site visit needed
Limekilns, Garreg	Whitford	II	Surveyed
Risk Score 2 - Extreme Risk			
Bakehouse with attached former byre at Garnychain	Trelawnyd & Gwaenysgor	II	
Former Smithy, Chester Street	Mold	II	Inappropriate works undertaken - enforcement issues

Risk Score 1 - Grave Risk	
4	Dwellings
1	Chapel
4	Quarry buildings
3	Ice houses
2	Stable block
2	Limekiln
2	Dovecotes
1	Land army hostel
4	Farm buildings
1	Gate Piers and wall
1	Bathroom structure
Risk Score 2 - Extreme Risk	
1	Bakehouse and byre
1	Smithy